





5800SMOKE V – Internal pics



Antenna trace built into PCB.
Bottom Side View



FCC ID: CFS8DLS8005MOKEV IC: 573F-58005MOKEV HVIN: 58005MOKEV This device complies with Part 15 of FCC rules and RSS-247 of Industry Canada. Operation is subject to the following conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation. Cet appareil est conforme à la partie 15 des règles de la FCC & de RSS-247 des Industries Canada. Son fonctionnement est soumis aux conditions suivantes: (1) Cet appareil ne doit pas causer d'interférences nuisibles. (2) Cet appareil doit accepter toute interférence reçue y compris les interférences causant une réception indésirable.

Model: 5800SMOKEV
Multi-Criteria Smoke Detector



WARNING

Please see Quick Installation Guide (R800-26634A) for important information about maintenance and battery life. Do not install in locations where temperature exceeds 100°F. Constant use at high or low temperature or high humidity may reduce battery life. Use only batteries specified, the use of other batteries may have a detrimental effect on alarm operation. Maintenance: Clean Alarm yearly by gently vacuuming the openings in the exterior of the Alarm.

Low Battery: 1 beep + 1 yellow flash every 48 sec
Alarm: 3 long beeps, repeating with flashing red LED
End Of Life: 3 beeps with 3 yellow flashes
Alarm Silence: 1 red flash every 8 sec
Sensitivity: = 1.82 to 2.92 % / ft Obsc.

R800-26682A
2/21 Rev A

Conforms to: UL STD 268
Certified to: ULC STD S529

For Servicing, return to:
Resideo Technologies / Ademco Inc.
12225 Rojas Dr, Suite 100
Resideo Dept.
El Paso, TX 79906

EN FRANÇAIS ↗



A055 - 0516
FW V1.1.4

A055 - 0516



Antenna trace built into the PCB.
Top and bottom side of PCB

