

FUNCTIONAL DESCRIPTION

The 5882AP-1 is a new board layout of our 5882AP receiver; (FCC ID: CFS8DL5882AP) it is identical in function and operation. This revision also replaces a microprocessor that went obsolete. The 5882AP-1 like the 5882AP, is used for reception of our 315 MHz transmitters such as the CFS8DL5816AP, and CFS8DL5804AP, etc.