

## Statement 15.19(3) in manual according to Tracking number 966041

Return address: PO Box 6, 7140 AA Groenlo, The Netherlands

American Certification Body, Inc  
Certification Department  
6731 Whittier Avenue, Suite C110  
McLean, Virginia 22101  
USA

Groenlo, 14 July 2014

Subject: Putting statement 15.19(3) in manual of SENSIT REALY NODE 2G of FCC ID: CGDRELAY

To whom it may concern,

With tracking number 966041 we, N.V. Nederlandsche Apparatenfabriek "Nedap", requested FCC to put the statement as mentioned in 15.19 (3):

*This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.*


in the manual.

FCC's answer:

*"The FCC allows the statement to be placed in a prominent location in the instruction manual or pamphlet supplied to the user".*

There for the above mentioned statement will only be in the manual.

Best regards,  
N.V. Nederlandsche Apparatenfabriek "Nedap"

  
Jacques Hulshof  
Approval Management