

Request putting statement 15.19(3) in the manual

Return address: PO Box 6, 7140 AA Groenlo, The Netherlands

ATCB
Attn.: Mrs. M. Bosley
Certification Department
6731 Whittier Avenue, Suite C110
McLean, Virginia 22101
USA

Groenlo, 13 November 2009

Subject : SENSIT Node (IR) labeling of statement 15.19(3) not able to add
FCC ID: CGDSENSNODE

Dear Mrs. Bosley,

We, N.V. Nederlandsche Apparatenfabriek "Nedap", declare that it is not possible to add the statement as mentioned in 15.19 (3):

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

next to the FCC ID, model number or the brand name on the bottom of the product due to size restrictions.

It also not possible to add a sticker to the side of the SENSIT Node (IR) since this material is Poly Ethylene to which it is not possible to attach a glued label.

NOTE: This material has been chosen, because dust is hardly able to stick on this product so it doesn't get too dirty.

There for we request the above mentioned statement be allowed to be in the manual, due to size and not able to add a sticker, based on the 2.935/2.936 rule part.

I hope you can honor our request

Best regards,
N.V. Nederlandsche Apparatenfabriek "Nedap"

Jacques Hulshof
Approbation Management

N.V. Nederlandsche Apparatenfabriek "Nedap"
Parallelweg 2
NL-7141 DC Groenlo
P.O. Box 6
NL-7140 AA Groenlo
T +31 (0)544 47 11 11
F +31 (0)544 46 34 75
E info@nedap.com
Handelsregister 08013836