




R37 WAS 100 OHM/1W.				WB
5	4025	9/6/94	DJU	
ADDED C3 AND C4 AT TB1.				SL
4	3921	1/18/94	GJP	
ADDED W1 FROM TB1-1 TO TB1-4.				WB
3	3917	1-12-94	DPK	
R2 WAS .05 OHM.				WB
2	3908	1-6-94	DPK	
ADDED: R3, R4, L2, C2, U2, DS3, DS4, F3, F4, TP5-TP8, R15-R22.				SL
CHANGED TITLE.				
1	3906	12/20/93	JML	
VOLTAGE AT J2-4 WAS -12V. DELETED THIRD SECTION OF BD. & CHANGED TITLE.				WB
0	---	9/8/93	CAR	

ITS CORPORATION				REV	ECN	DATE	APV
THIS PRINT IS THE PROPERTY OF ITS CORP. IT SHALL NOT BE COPIED WITHOUT PERMISSION.				TITLE			
				SCH. BIAS PROTECTION BD. 4 SECTION (1500-3114)			
REV	ECN	DATE	APV	DWN			
FINISH	CHK	CAR	5/24/93	DWG. NO.			
---				1500-3114			
---				REV			
---				5			
---				SCALE --- SHEET 1 OF 1			