


8.5 Inside View



8.6 Inside View




REPORT NO : HEI-RF-9807002


FCC ID : CKLHT-2595C

DATE : JULY. 13, 1998


8.7 Inside View




8.8 Component side of Main board




8.9 Solder side of Main board




8.10 Component side of CRT board




8.10-1 Component side of CRT board




8.11 Solder side of CRT board




8.12 Component side of BNC board




8.13 Solder side of BNC board



8.14 Component side of FRONT CONTROL board



8.15 Solder side of FRONT CONTROL board



8.16 CRT View

