MFOURTEL MEXICO S.A. DE C.V. ADD: Av. Ejército Nacional 436 Piso 3 Chapultepec Morales Miguel Hidalgo D.F 11570, Mexico Tel: 00886075526739633 Fax: 075526739120 Email: Xin.Li@m4tel.com

Attestation Letter

2017-12-25

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir or Madam:

The RF chip, model: MT6625L installed in our product LTE Mobile Phone; FCC ID: CLNM4B1; which supports 5G Wifi function. For use in the US market, this chip will not support/enable 5G Wifi functions. The 5G Wifi has been shielded by the manufacturer by using the software.

And the chip MT6737 which supports 2G/3G/4G function, but only used GSM850/1900, WCDMA Band2/5, LTE 2/4/7/12, the other band has been shielded by the manufacturer by using the software.

Sincerely,

.

lixin Signature:

Xin Li

Manager