

MFOURTEL MEXICO S.A. DE C.V.

Address: Av. Ejército Nacional 436 Piso 3 Polanco V sección Miguel Hidalgo Mexico DF 11560

Tel: 00886075526739633

Fax: 075526739120

Attestation Letter

March 17, 2016

To:

Bay Area Compliance Laboratories Corp.
1274 Anvilwood Avenue
Sunnyvale, CA 94089

Dear Sir or Madam:

The RF chip, model: MSM8909, installed in our product Smart Phone, model: M4 SS4456, which supports LTE band5 and band25 functions. For use in the US this chip will not support/enable the LTE band5 and band25 functions. The LTE band5 and band25 function has been shielded by the manufacturer using the software

Sincerely,

Signature: *Xin Li*

Xin Li

Manager