


# INTERTEK TESTING SERVICES

Report No.: HK10060857-1  
 Sample No.: 1/3



Duty Cycle:

$$= \frac{4 \times 0.74}{100} \text{ ms}$$

$$= \frac{2.96}{100} \text{ ms}$$


$$= 0.0296$$

Average Factor:

$$= 20\log(0.0296)$$

$$= -30.5 \text{ dB}$$

Date: 29.MAY.2010 09:21:48




Date: 29.MAY.2010 09:22:25

**Timing Plot – Pursuant to FCC Part 15 Section 15. 247 Requirement**

# INTERTEK TESTING SERVICES

Report No.: HK10060857-1  
Sample No.: 1/3



Date: 29.MAY.2010 09:24:06

Timing Plot – Pursuant to FCC Part 15 Section 15. 247 Requirement

Code: FCC15C\_c / Effective Date: 04 Aug 2009