



# Intertek Testing Services

## ETL SEMKO

Report No.: 0107608

Tested By: Ben, Report No.: 0107608

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



Ctrl No.: N/A



# Intertek Testing Services

## ETL SEMKO

Report No.: 0107608

Tested By: Ben, Report No.: 0107608

### Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.54500	23.1	48.0
0.68000	22.4	48.0
0.88500	21.3	48.0
1.09500	19.8	48.0

\* limit

Ctrl No.: N/A