



Changes:
15/5/2000

1. C3 was 30pF, now 2pF
2. C5 was 150pF, now 100pF
3. R6 was 33K, now 26K
4. C7 was 2pF, now 3pF
5. C8 was 6pF, now 8pF
6. C8 was 3pF, now 4pF
7. Add C12, C13, both 1000pF.

Changes:
13/3/2000

1. C7 was 4pF, now 2pF
2. C8 was 1pF, now 3pF
3. C10 was 7pF, now 12pF
4. R4 was 1.5K, now 1K
5. R7 was 15K, now 20K
6. R10 was 2.2K, now 6.8K
7. L5 was 1uH, NOW 0.8uH.

Title 842 RADIO RECEIVER		COMPULTE LTD.
Designed By:	Drawn By:	T.F. PO HOANG ST., KWUN TUNG, KUNMUNAN
Size: Ordinal Number:	Revision: 1	HOANG KONG
File: E:\My Documents\842\842_2.sch Date: 19-Jul-2000 Time: 13:20:23 Sheet 1 of 1		