
9. SETUP PHOTOS


ANTENNA PORT MEASUREMENT SETUP



Page 29 of 35


POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP







Page 30 of 35

RADIATED RF MEASUREMENT SETUP CONFIGURATION







Page 31 of 35



Page 32 of 35

RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







UL VERIFICATION SERVICES INC. 1285 WALT WHITMAN RD, MELVILLE, NY 11747, USA TEL: (631) 271-6200 FAX: (877) 854-3577 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 33 of 35

RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





Page 34 of 35