



EchoStar Technologies L.L.C.
90 Inverness Circle East
Englewood, CO 80112
(303) 706-5234

March 17, 2016

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: DKNWWT

To Whom It May Concern:

The ID:072 client software and associated drivers:

- will not initiate any transmission on DFS frequencies without initiation by a master device
- will not transmit beacons on DFS frequencies/channels
- do not support ad-hoc or peer to peer networks

Sincerely,

Ian Schroeder
Regulatory Compliance Engineer
EchoStar Technologies L.L.C.