

EchoStar Technologies L.L.C. 90 Inverness Circle East Englewood, CO 80112 (303) 706-5234

July 14, 2011

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

RE: DKNYT1300

To Whom It May Concern:

This letter covers the tune up procedure details. The transmitter circuit used in this product has \*no\* tune up features. The circuit will function at its desired power and frequency upon assembly.

Sincerely,

Ian Schroeder

Regulatory Compliance Engineer

A Schule-