



**FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046**

Aug. 15, 2014

Subject: Permissive Class II change for FCC ID: DT91200769

Dear Sir,

The FM transmitter, Model No.: 1200769, FCC ID: DT91200769 needs to apply for the Class II Permissive Change due to the antenna out and general ground are separated. We evaluated that the changed would NOT affect the RF characteristics except for the Radiated Spurious Emission test (30MHz ~ 1GHz).

The product has Radiated Emission test and compliance with the 47 CFR Part 15 Subpart C 15.239 and relative regulations. For more details, please refer to the test report.

If you have any question, please feel free to contact me.

Sincerely Yours,

A handwritten signature in blue ink, reading "Jimmy Yang". The signature is fluid and cursive, with "Jimmy" on the top line and "Yang" on the bottom line.

Jimmy Yang
Engineer
Intertek Testing Service Taiwan Ltd.