



Federal Communications Commission  
7435 Oakland Mills Road  
Columbia MD 21046

Attention: Application Examiner / Review Engineer  
Subject: Request to change identification per section 2.933 of FCC rules

Date: July 24, 2019  
Reference: FCC ID: **DWNSOMFYPLUG** (new FCC ID)

To: The Commission:

This Change of Identification request applies for a new FCC ID: **DWNSOMFYPLUG** as established in 47CFR 2.933(b) for a currently approved device. This application by Somfy Systems will establish a new FCC ID under **DWN** grantee code for the purpose of marketing. The original grant to FCC ID: 2AB2Q6BPLZA0 (original ID) will remain in effect.

An authorization letter by LEEDARSON LIGHTING CO., LTD. is attached.  
Per 2.933(b)

1. The original identification is FCC ID: 2AB2Q6BPLZA0
2. The original grantee date is 07/18/2019(DTS)
3. The equipment is electrically identical. Only the FCC ID number and model name is different.
4. The original test results are application and representative of this changed device .
5. Exterior photographs are included in this application.

This following files are electronically submitted as attachments:

Cover Letter  
External Photos  
FCC ID label format location

Sincerely yours,

Somfy  
James P. Hellander  
Engineering Manager  
609-395-1300 #2662  
Jim.Hellander@somfy.com

SOMFY SYSTEMS, INC.  
121 Herrod Boulevard  
Dayton, NJ 08810  
Telephone: (609) 395-1300  
Fax: General (609) 495-8117  
Fax: Sales (609) 495-8118  
www.somfysystems.com