


3. General test set-up for radiated measurements.




Report No.: 23868RET.101	Page: 4 of 6
	Annex B
Date: 2006-04-03	AGY-737054-0000.A0

FET18_00.DOC



4. Test set-up for radiated measurements below 1 GHz.




Report No.: 23868RET.101	Page: 5 of 6
23000KE1.101	Annex B
Date: 2006-04-03	AGY-737054-0000.A0

FET18_00.DOC



5. Test set-up for radiated measurements above 1 GHz.



Report No.: 23868RET.101	Page: 6 of 6
200001221101	Annex B
Date: 2006-04-03	AGY-737054-0000.A0

FET18_00.DOC