

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

	Amplifier	Antenna
Below 30 MHz	Y-axis	Z-axis
Above 30 MHz	Horizontal: X-axis / Vertical: X-axis	Horizontal: X-axis / Vertical: X-axis

X-axis



X-axis



Y-axis



Y-axis




Z-axis



Z-axis



With/Without Tag



With Tag



Without Tag (Worst)

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Frequency Tolerance




Photo 1

End of Report