



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

February 19, 2003

RE: FCC ID: E5MDS-1710

Attention: Tri M. Luu

I have a few comments on this Application.

1. Please provide the factory 'tune up' procedures used to set maximum peak deviation.
2. The values in the emissions designator and the measured values in the data do not seem to correlate very well. Please explain.
3. The low power listed on the grant and the low power listed in the report are not the same. Please correct the 731 to show the maximum measured low power setting values. (20.84dBm or 121mW). Alternately please explain why the measured power is not what is listed on the 731 (the FCC requires TCBs to list the measured readings on grants).

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.