



GE MDS

175 Science Parkway, Rochester, New York 14620 USA
(585) 242-9600 Phone
(585) 242-9620 Fax
December 7th, 2015

FEDERAL COMMUNICATIONS COMMISSION

7435 Oakland Mills Road
Columbia, MD 21046
U.S.A.

Subject: Tune Up procedure for the LN900

Applicant: GE MDS LLC.

Product: MDS LN900


FCC ID: E5MDS-LN900

Dear Sir/Madam,

The LN900 has no customer or user tune up procedure. This is a DSP/microprocessor controlled based unit. All RF power settings, modem settings, are saved into non-volatile ram. The unit is factory calibrated and there are no user calibration settings available. There are no tune up procedures available to the end user. All tune ups must be done by the GE MDS factory.

If you have any queries, please do not hesitate to contact me at 585 242-8440:

Yours truly,

Signed:  Name: Dennis McCarthy

Dennis McCarthy

Agency Compliance Engineer

GE MDS

175 Science Parkway

Rochester NY 14620

Phone (585) 242-8440

Email Dennis.McCarthy2@GE.com