Report No. 0383-08 (FCC ID: E675JS0046)

ATTESTATION STATEMENT

SUMMARY:

All tests according FCC Part 2, Paragraphs 2.1046, 2.1051, 2.1053, and Part 42, Paragraph 24.238 were

■ - Performed

The Equipment Under Test

■ - Fulfills FCC Part 2, Paragraphs 2.1046, 2.1051, 2.1053, and Part 42, Paragraph 24.238 requirements.

- TÜV PRODUCT SERVICE, INC. -

Responsible Engineer:

Jim Owen

(EMC Engineer)