

Correspondence by Project

Project Number:

1424979456

Correspondence Number	Memo
EF400128-1	1) Please provide a certification contract. Certification Contract has been provided. 2) Please provide a diagram showing the location of the FCC ID label. A corrected FCC ID label has been provided. 3) The user manual does not have the entire compliance statement. Please provide a corrected user manual. A corrected Users Manual has been provided. 4) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." A corrected Block Diagram has been provided. 5) The external photos do not show all of the sides. Please provide additional external photos. Correct External Photos have been provided. 6) The internal photos show an RF shield. Please show additional photos with the shield removed. Correct Internal Photos have been provided. 7) Please provide a modification attestation letter. Modification Attestation Letter has been provided.