

WARNING!
RISK OF DAMAGE TO ELECTRONICS.
DO NOT CONNECT TO THE PARTS INSIDE.
ELECTRICAL SHOCK HAZARD.
INTERNAL COMPONENTS.
DO NOT CONNECT BATTERY.

For operation of the alarm, please refer to the user manual. Installation, operation, testing, maintenance, evacuation planning, and repair service is to be provided with this equipment.

US Fire Protection Regulatory Information
Install according to NFPA 72 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02269). Printed information describing proper installation, operation, testing, maintenance, evacuation planning, and repair service is to be provided with this equipment. Made in China

Battery and System Test.
To test the console, notify the Central Station of the test, disconnect AC power supply from the wall outlet and press user instructions for details.


10021767 X





To test the console, notify the Central Station of the test, disconnect AC power supply from the wall outlet and press user instructions for details.

10021767 X1



70-4C-EKE
18230D1-B

winbond
W9864G6KH-6
1836H
68195B200ZZ

NUVOTON
NUC710ADNARM
822AB2819B104-AA2FC

11K67372S21

FP
0598
479
6.6

470

PTC1



FIRMWARE v1.08



S/N 1862020009972001

J3




2GIG

© 2017

10018937

REV A

PA CP 5 94V-0
KT E243951
. 1834



J1
U1
C2
C21
FL5
C18
FL3
FL4
C19
FL2
C13
U2
R2
C10
C14
L2
C4
R5
C3
C15
U3
Y1
R1
R6
R7
R4
R3



Telit LE91081-NA

827
86730
MADE IN CHINA

827
86730
MADE IN CHINA

00013

IMEI: 0153070000000044

FCC ID: R17LE910NAVZ
IC: 5131A-LE910NAVZ
Designed in Italy, Made in China

10021254 X3

FIRMWARE v1.21

2GIG - GC25 - 345E
1828020008512140

SECURITY & CONTROL



6X ^ EFWMNF

IMEI: 01351800 - 3811342

2GIG - GC3GAX - A
SN: 1703120004274590

Telit HE910-NAR
SNR: 007130071974248
Model: HE910-NAR
FCC ID: R17HE910NA
IC: 5131A-HE910NA
Designed in Italy, Made in China

FIRMWARE V1.21
2GIG - GC25 - 345E
1828020008512135

SECURITY & CONTROL
10021254 X
PORTTEK
© 2019

8670
802M