

The Intermec logo is written vertically in a bold, blue, sans-serif font. To its right is a large, faint, light-blue graphic of a globe with latitude and longitude lines.

**Intermec
Technologies
Corporation**

6001 36th Avenue West
Everett, Washington 98203
United States
tel 425.348.2600
fax 425.355.9551
www.intermec.com

August 24, 2009

Michael Kuo
Compliance Certification Services, Inc.
47173 Benicia Street, Fremont, CA 94538

Dear Mr. Kuo,

This letter is a request that Compliance Certification Services (CCS) initiate a Class II Permissive Change to Intermec model CN50, FCC ID: EHA-01CN50 pursuant to FCC Part 2.1043.

This change involves only the inclusion of CDMA 1x and EV-DO WWAN capability to the CN50 by means of a software change to the Qualcomm radio module FCC ID: J9CFENWAY-1. There are no hardware changes to the CN50 associated with this request.

The result of this effort will be to make available CDMA protocol communication to the CN50 based on the recent Class II Permissive Change to the Qualcomm radio module FCC ID: J9CFENWAY-1. The change from UMTS to CDMA or from CDMA to UMTS protocols in the CN50 will not be user accessible and can only be performed at the factory or at an authorized service facility by trained personnel.

Please advise me when this effort has been completed. And if you have any questions or concerns relating to this request, do not hesitate to contact me by telephone at (425) 267-2919, or by email at wayne.rieger@intermec.com.

Sincerely,

A handwritten signature in black ink, appearing to read "Wayne F. Rieger".

Wayne F. Rieger
Radio Compliance Engineer
Intermec Technologies Corporation
6001 36th Avenue West
Everett, WA 98203-1264
425-267-2919