


UMTS/CDMA radio located below this shield

System Board with 2nd shield





MAIN ▲
T77Z204.10 HF
REV: 04L4
MEID A1000004BC4852
IMEI 355096040133653
Made in China 1101145

BAL
Made in Malaysia
CAP-X
4.5V
NIB191
0.14F 70mAh

F12E04T4
T77Z204T10 HF
45006078-04L4
QC PN: 20-VM173-P3

SDX AMVER 12
145-462-007
GHT 2009 INTERMEC
ASSEMBLED IN SINGAPORE
Taiwan

VLSIN11001969
KL Ref: CC-40620701

TOPSEARCH
SR17428/18
84V-0 TS-8V01C
C133
C134
C136
C137
C138
C139
C140
C141
MADE IN CHINA
ASSEMBLED IN SINGAPORE



RESET
SW1
SW2
C15
C123
C16
C124
C17
C125
C18
C126
C19
C129
C20
C130
C131
C132
145-411-001
COPYRIGHT
2009 INTERMEC


VLSIN11001969
KL Ref: CC-48500801

WLAN/BLUETOOTH
RADIO



Back of System Board with and without shield





" Radio modu



" Radio module with shield

UMTS/CDMA Radio Module

Figure 1 Module Top View Internal Photograph (Shield Removed)




Figure 2 Module Bottom View External Photograph (Label Removed)

