

31-December-2008

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046 Intermec Technologies Corporation

6001 36th Avenue West Everett, Washington 98203 United States tel 425.348.2600 fax 425.355.9551 www.intermec.com



To whom it may concern,

We, Intermec Technologies, hereby attest that the client software and associated drivers used with the DDIB radio module will not initiate any transmission on DFS frequencies. This includes transmissions for beacon ad-hoc peer-to-peer modes.

Sincerely,

Sean MacKellar

Compliance Engineer

Intermec Technologies Corporation

See gratell

6001 36th Avenue West Everett, WA 98203-1264

425-356-1765