




Photographs of ID Label for module ITRM91501X04.
Board Set Label.

Intermec Technologies Corporation Everett, WA 98203	
No user-serviceable parts. Aucune pièce réparable par l'utilisateur. Keine vom Benutzer zu wartenden Teile. Ninguna pieza puede ser reparada por el usuario.	SERVICE & SUPPORT USA 1-800-755-5505 CANADA 1-800-668-7043 Others contact your local Service Representative.
Complies with (En conformité avec): U.S.A. FCC PART 15 CANADA ICES-003 See manual (Reférez - vous à la documentation).	FCC ID: EHAITRM91501 Made in Singapore
This product is covered under and protected by one or more of the following patents: 5,763,867 5,828,693 5,850,187	
 = 9V, 2A	MODEL: ITRM91501 C/N: S/N: MFD:

Serial box label.

Intermec Technologies Corporation Everett, WA 98203		Made in U.S.A.
No user-serviceable parts. Aucune pièce réparable par l'utilisateur. Keine vom Benutzer zu wartenden Teile. Ninguna pieza puede ser reparada por el usuario.	SERVICE & SUPPORT USA 1-800-755-5505 CANADA 1-800-668-7043 Others contact your local Service Representative.	
Complies with (En conformité avec): U.S.A. FCC PART 15 CANADA ICES-003 See manual (Reférez - vous à la documentation).	CONTAINS TX FCC ID: EHAITRM91501	
This product is covered under and protected by one or more of the following patents: 5,763,867 5,828,693 5,850,187		
 = 9V, 2A		MODEL: ITRF91501 C/N: S/N: MFD:

ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Intermec Technologies Corporation
MODEL: ITRM91501X04
Test #: 0200205 FCCID#: EHA-RM91501X04
Test to: FCC Parts 2 and 15