



6001 36<sup>th</sup> Avenue West Everett, Washington 98203 United States **tel** 425.348.2600 **fax** 425.355.9551 www.intermec.com



30-MAY-2006

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

## RE: Tune-up Procedure for FCC ID: EHAMC75 GSM Module in 700C Hand Held Computer

To whom it may concern,

The MC75 quad-band GSM module requires no adjustments of components after assembly. The 700C hand held computer host device, likewise, requires no adjustments of components after assembly. Settings for radio and hand held computer operation require specialized equipment only available to Intermec manufacturing and service personnel.

Please Contact me if there are any questions.

Yours truly,

Scott J. Holub

Regulatory Compliance Supervisor Intermec Technologies Corporation

550 Second Street S.E.

Cedar Rapids, IA 52401 USA