



Report No.: 0010212

Tested By: Ben, Report No.: 0010212

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1



Intertek Testing Services

ETL SEMKO

Report No.: 0010212

Tested By: Ben, Report No.: 0010212

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
-------	------	------	-------	----------	--------	-------	--------	-------

450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB
------	-----	----	-----	----	------	------	--------	------

Final Measurement Results:

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

14.16500	36.0	48.0
----------	------	------

* limit exceeded