


EMC Technologies Report Number: M050322_Cert_WLL4070_11abg_DTS_BT

APPENDIX K1
Harmonics - Atheros 802.11a



Harmonics – Channel 149

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.73 dBm VBW 300 kHz
15 dBm 5.68937876 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 14:41:02



Harmonics - Channel 152

Ref Lvl	Marker 1 [T1]	RBW	100 kHz	RF Att	30 dB
15 dBm	-0.85 dBm	VBW	300 kHz		
	5.68937876 GHz	SWT	9.8 s	Unit	dBm




Date: 24.MAR.2005 14:38:07



Harmonics - Channel 157

Marker 1 [T1]	RBW	100 kHz	RF Att	30 dB
Ref Lvl	-1.07 dBm	VBW	300 kHz	
15 dBm	5.76753507 GHz	SWT	9.8 s	Unit dBm




Date: 24.MAR.2005 14:46:04



Harmonics - Channel 160

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -0.15 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 14:35:41



Harmonics - Channel 165

Marker 1 [T1]	RBW	100 kHz	RF Att	30 dB
Ref Lvl	-1.73 dBm	VBW	300 kHz	
15 dBm	5.68937876 GHz	SWT	9.8 s	Unit dBm



Date: 24.MAR.2005 14:41:02

