



March 24, 2011

To: FCC

From: SIEMIC, INC.

RE: Request for supersede of test report exhibits

Applicant: Fujitsu Limited, FCC ID: EJE-WL0025,

There is a RF power conversion typo error on Section 1.3. it was listed 0.0712W , it should be 0.0172W .
therefore, we are asking to kindly replace the UNII Report part 1 with revised copies.

You can find the changes on section 1.3 of the revised test report,

Thank you,

Annie Jiang
SIEMIC, INC.
2206 Ringwood Ave.,
San Jose, CA 95131
Tel: 408-526-1188 Ext 209
Fax: 408-526-1088