

TIMEX

TIMEX. It takes a licking and keeps on ticking.®

Timex Corporation
555 Christian Road
P.O. Box 310
Middlebury, CT 06762-0310

203-346-5000
www.timex.com

May 19, 2004

Joseph Danisi
Underwriters Laboratories Inc.
EMC Facility
1285 Walt Whitman Road
Melville, NY 11747


Dear Mr. Danisi,

Timex Corporation hereby requests that the following documentation, submitted to the FCC, Industry Canada, or any other country communication authority in support of the Timex M185 GPS Transceiver product, be classified as confidential:

- Schematic diagrams
- Block diagrams
- Product Specifications
- Bill of Materials

The reason for not making this information public is to prevent our competitors from gaining access to proprietary information.

Sincerely,



John Davino
Compliance/QC Test Engineer