

Date: June 23, 2008

To: FCC

From: Larry Canady, larry.canady@bsci.com
Guidant Corporation
4100 Hamline Ave. N.
Arden Hills, MN 55112

Subject: ID Label and Location – Application for Equipment Certification, FCC ID:
ESCCRM647608

The Guidant Corporation (a wholly owned subsidiary of Boston Scientific Corporation doing business as Boston Scientific Cardiac Rhythm Management, hereinafter referred to as BSC) Model 6476 LATITUDE™ Communicator label and location of the label are shown.

Figure 1. BSC Model 6476 Label



Figure 2. BSC Model 6476 Communicator Label Located on Bottom Housing (for reference only)



Note: The Class II symbol shown here has since been removed from the Model 6476 label. In addition, the Bluetooth module FCC ID has since been corrected to read POOWML-C40 and not POOWML-C40XX as shown.