### The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission <u>LSG25-2</u> <u>NK00041215</u> <u>AS</u> BD

Radiated Emission - Base Unit (Brand: Tenpao)

Front View



Rear View

### The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission LSCOSC-2 HK09OA1275 ALC BD 3

Radiated Emission - Base Unit (Brand: Sunstrong)

#### Front View



Rear View

### The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission – Base Unit

Howasser		
	RADIATED Model No.: LS6215-2	
	Job No.: <u>HK09041275</u>	
	A B	

Front View




Rear View

Conducted Emission - Model: LS6225-2 (Brand: Tenpao)




Front View



Right Side View

Conducted Emission - Model: LS6225-2 (Brand: Tenpao)




Left Side View

Conducted Emission - Model: LS6225-2 (Brand: Sunstrong)




Front View



Right Side View


Conducted Emission – Model: LS6225-2 (Brand: Sunstrong)




Left Side View

# The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: LS6215-2



Front View



Right Side View

## The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: LS6215-2



Left Side View