

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission – Base Unit (adaptor type B)



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission – Base Unit (adaptor type A)



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission – Handset



Front View



Rear View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: DS6311-2 (adaptor type A)



Front View



Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: DS6311-2 (adaptor type A)



Left Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: DS6321-2 (adaptor type A)



Front View



Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: DS6321-2 (adaptor type A)



Left Side View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Ringing

Conducted Emission – Model: DS6311-2 (adaptor type A)



Front View



Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Ringing

Conducted Emission – Model: DS6311-2 (adaptor type A)



Left Side View