### The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission - Base Unit (with adaptor "Salcomp")

Front View



Rear View

### The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission - Base Unit (with adaptor "Ten Pao")



Front View



Rear View

## The Worst Case Configuration Photographs – Mode: Transmission


Radiated Emission TLA D.2. ILA D.6.6.8-1 ILA D.6

Radiated Emission - Handset

Front View


	PH WERE AND
a sure man	
	and the second state of th
NUCL - The State	
A CONTRACTOR OF A CONT	
Radiated Emission	
TL92271	and the second
нки // 0668-/	

# The Worst Case Configuration Photographs – Mode: Charging



Conducted Emission (with adaptor "Salcomp")

Front View



Right Side View

## INTERTEK TESTING SERVICES The Worst Case Configuration Photographs – Mode: Charging

Conducted Emission (with adaptor "Salcomp")

Left Side View

#### FCC ID: EW780-7764-00 IC: 1135B-80776400