

Reason for Permissive Change Request

The following changes were made to the SBG900:

- 1) A small piece of copper tape which grounds the tuner shield to the back plate was added.
 - 2) A small cut was made into the insulation of the external antenna's cable. Its shield was then grounded to the main circuit board.
- No other changes were made.

Photos of the changes and a new test report are being uploaded.