



Digital Security Controls
3301 Langstaff Road
Concord, Ontario Canada L4K 4L2

Tel: 905-760-3000
Fax: 905-760-3030
Toll Free: 888-888-7838
www.dsc.com

JANUARY 12, 2011

To whom it may concern

This letter is a notification regarding the differences between the two hardware UA564 Rev 01 and Rev 02 revision board of Model: WT4901 are as follows:

- Added electronic circuit for impedance isolation between RX/TX circuits
Added Component U8 and C19 (bypass cap)
- Added microprocessor control line for RX/TX switching
Added Component R31
- Added extra matching to TX circuit for improved harmonic suppression
Added C59, C60, L3, C57, and changed R5 to C58
- Removed parts from receiver matching for ease of layout
Removed R41, R42, R70, C47, C48

The changes above have no impact on the RF compatibility with the wireless alarm panel. The protocol and data transmission packet information have not been altered as it was initially tested.

Should you require addition information regarding the above changes, please contact me at Ext. 2706.

Thank you,

Dan Nita, Approvals Manager