



January 10, 2006

Attn: Director of Certification

Re: Tune-up Procedure

The Digivance® Long Range Coverage Solution 800 MHz System model numbers DGLV-112XXSYS and DGLV-122XXSYS employ a solid-state design that does not require a tune-up procedure.

Sincerely,

A handwritten signature in cursive script, appearing to read "Dave Conyers".

Dave Conyers
Vice President of Engineering
Tele: 952 403-8424
Fax: 952 403-8858