

The Rated RF power output in watts for this equipment should be 1.35 rather than 12.5.