

## USER'S MANUAL FCC REGULATORY NOTICE

### Service Return Address:

Schlumberger RMS, Inc.  
313 North Hwy. 11  
West Union, SC 29696

### 47 CFR, Part 15, SUBPART 15

The CENTRON with RMC module has been tested and found to comply with the limits for an intentional radiator, pursuant to 47 CFR Part 15, Subpart C, Paragraph 247 of the FCC rules. This equipment generates, uses, and can radiate radio frequency energy. If not installed and used in accordance with the instructions, it may cause interference to radio communications.

The limits are designed to provide reasonable protection against such interference in a residential situation. However, there is no guarantee that interference will not occur in a particular situation. If this equipment does cause interference to radio or television reception, which can be determined by tuning the equipment on and off, the user is encouraged to try and correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna of the affected radio or television.
- Increase the separation between the equipment and the affected receiver.
- Connect the equipment and the affected receiver to power outlets on separate circuits.
- Consult the dealer or experienced radio/TV technician for help.

Changes or modifications not expressly approved by Schlumberger Resource Management Services, Inc. could void the user's authority to operate the equipment.