Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 <u>http://www.rheintech.com</u> Client: Fleetwood Group, Inc. Model: VL4B Standards: FCC 15.231/IC RSS-210 FCC/IC ID: FBRVL4B/1859A-VL4B Report #: 2010155

#### Appendix K : Manual

Please refer to the following pages.

## **USER MANUAL**

# **VL4B Module**



©Copyright 2007 Fleetwood Group, Inc., Electronics Division. All rights reserved. Licensed software products are owned by Fleetwood Group, Inc. or its suppliers and are protected by United States copyright laws and international treaty provisions.

Fleetwood Group, Inc. products are covered by U.S. and foreign patents, issued and pending. Information in this publication supersedes that in all previously published material. Specifications and pricing are subject to change without notice.

Printed in the U.S.A.

Fleetwood Group, Inc. Electronics Division 11832 James St. Holland, Michigan 49424

www.fleetwoodgroup.com

Sales: 1-800-257-6390 Technical Service: 1-888-GO-REPLY (467-3759)

Reply<sup>®</sup> is a registered trademark of Fleetwood Group, Inc. Other trademarks contained herein are the property of their respective holders.

#### **Revision History:**

]	Rev	Date	Description
A	A	8/11/2010	Original



### Table of Contents

1.0 VL4B MODULE	4
1.1 DESCRIPTION	4
1.2 BATTERY REPLACEMENT	
1.3 FCC AND IC	4
1.4 Standards and Guidelines	4
1.5 FCC/IC COMPLIANCE	5



### 1.0 VL4B Module

#### **1.1 Description**

The VL4B Module is an infrared transmitting badge with a RF supervisory signal. The VL4B Module contains a low power RF transmitter chip which is controlled by a micro processor. The frequency synthesizer for generation of the RF output carrier is received from a low frequency external crystal. A crystal resonator chip runs the micro processor device. When an RF transmission needs to be generated the data from the microprocessor is sent to the RF chip. The modulation used by the radio frequency chip is on/off key at 433.92MHz. The RF antenna is a PCB etched loop. The VL4B is powered by a three-volt battery.

Both infrared and RF signals are independent of each other. Both infrared and RF signals contain recognition code to identify the badge, along with motion status, battery status, and switch information.

There are two ways that theVL4B Module can send RF transmission packets. The first is an automatic transmission per FCC regulations section 15.231 part (a) paragraph three, which states that the periodic rate of transmission does not exceed one transmission of not more than one second duration per hour of each transmitter. The second type of RF transmission occurs when a button is pressed on the badge. The RF transmission packets cease operation when the button is released.

#### **1.2 Battery Replacement**

The VL4B is powered from a 3V battery. The battery is replaceable. To replace battery, open the case, remove the old battery, and replace with a new battery noting its polarity. The negative side of the battery should be facing the PCB.

#### 1.3 FCC and IC

VL4B Module Responsible Party Pertaining to the Declaration of Conformity

> Fleetwood Group, Inc. 11832 James Street Holland, MI 49424 Attn: Product Service Coordinator Phone: 888-467-3759

#### 1.4 Standards and Guidelines

This device complies with the following USA/Canada Regulations:

- > The USA Federal Communications Commission (FCC) Rules and Regulations
- Industry Canada Rules and Regulations

This device complies with the following national and international standards:

- FCC Part 15B, 15.231e (10-01-09)
- ► IC RSS-210 Issue 7



#### **1.5 FCC/IC Compliance**

This device complies with Part 15 of the FCC Rules and RSS-210 of the Industry Canada Rules. Operation is subject to the following two conditions: (1) this device may not cause interference and (2) this device must accept any interference, including interference that may cause undesired operation of the device. The user is cautioned that changes or modifications to the device that are not approved by the manufacturer could void the user's authority to operate the device.