FCC ID: FDI-09101560-0
Description of Permissive Change
-
This report is prepared for FCC class II permissive change. Difference compared with the
original report is adding the power adapters and adding second source of CPU
(RTL8366RB) and product name.

Report No.: RF971215L14A