



Internal photographs
Circuit Side Antenna



Solder side





Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore - Amtech Technology Center
Model: 05986
Test #: 170601
Test to: 47CFR Parts 2, 90 and RSS-137
File: 05986 Short Term Conf IntPho

SN: ENG1
FCC ID: FIH05986
IC: 1584A-05986
Date: June 30, 2017
Page 1 of 3

Power Regulator board




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore - Amtech Technology Center
Model: 05986
Test #: 170601
Test to: 47CFR Parts 2, 90 and RSS-137
File: 05986 Short Term Conf IntPho

SN: ENG1
FCC ID: FIH05986
IC: 1584A-05986
Date: June 30, 2017
Page 2 of 3

Side View of transmitter board and power regulator



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore - Amtech Technology Center
Model: 05986
Test #: 170601
Test to: 47CFR Parts 2, 90 and RSS-137
File: 05986 Short Term Conf IntPho

SN: ENG1
FCC ID: FIH05986
IC: 1584A-05986
Date: June 30, 2017
Page 3 of 3