



Date: 4 DEC 2020 19:58:03


MIMO A-802.11ax-40MHz-Ch46-5230MHz-HE0




MIMO B-802.11ax-40MHz-Ch46-5230MHz-HE0



SISO A-802.11ax-80MHz-Ch42-5210MHz-HE0




MIMO A-802.11ax-160MHz-Ch50-5250MHz-HE0-996/S67




MIMO B-802.11ax-160MHz-Ch50-5250MHz-HE0-996/S67

**U-NII-2A**




**SISO B-802.11a-20MHz-Ch56-5280MHz-6**




Date: 4 DEC 2020 19:33:05

**MIMO A-802.11n-20MHz-Ch52-5260MHz-HT8**




Date: 4 DEC 2020 19:38:34

**MIMO A-802.11n-40MHz-Ch54-5270MHz-HT8**





**MIMO B-802.11n-20MHz-Ch52-5260MHz-HT8**




**MIMO B-802.11n-40MHz-Ch54-5270MHz-HT8**

Test Report N° 200611-01.TR01




MIMO A-802.11ac-80MHz-Ch58-5290MHz-VHT0

MIMO B-802.11ac-80MHz-Ch58-5290MHz-VHT0




SISO A-802.11ac-160MHz-Ch50-5250MHz-VHT0



Date: 4 DEC 2020 19:47:17



MIMO A-802.11ax-20MHz-Ch52-5260MHz-HE0

MIMO B-802.11ax-20MHz-Ch52-5260MHz-HE0




Date: 4 DEC 2020 19:57:08


## MIMO A-802.11ax-40MHz-Ch54-5270MHz-HE0




## MIMO B-802.11ax-40MHz-Ch54-5270MHz-HE0



## MIMO A-802.11ax-80MHz-Ch58-5290MHz-HE0



## MIMO B-802.11ax-80MHz-Ch58-5290MHz-HE0




## MIMO A-802.11ax-160MHz-Ch50-5250MHz-996/S67-HE0

## MIMO B-802.11ax-160MHz-Ch50-5250MHz-996/S67-HE0

### C.1.3 Undesirable emission limits: out of band (Conducted)


#### U-NII-1

## SISO A




Date: 7 DEC 2020 09:43:54

BE-R-LOW, SISO-A, 802.11a20-6Mbps, Ch36




BE-R-LOW, SISO-A, 802.11n20-HT0, Ch36




Date: 4 DEC 2020 16:27:27


BE-R-LOW, SISO-A, 802.11n40-HT0, Ch38



BE-R-LOW, SISO-A, 802.11ac80-VHT0, Ch42




BE-R-LOW, SISO-A, 802.11ac160-VHT0, Ch50




Date: 4 DEC 2020 16:31:49


BE-R-LOW, SISO-A, 802.11ax20-HE0, Ch36



BE-R-LOW, SISO-A, 802.11ax40-HE0, Ch38




BE-R-LOW, SISO-A, 802.11ax80-HE0, Ch42




BE-R-LOW, SISO-A, 802.11ax160-HE0, Ch50


## SISO B



BE-R-LOW, SISO-B, 802.11a20-6Mbps, Ch36




BE-R-LOW, SISO-B, 802.11n20-HT0, Ch36




Date: 7.JAN.2021 16:30:05


BE-R-LOW, SISO-B, 802.11n40-HT0, Ch38




BE-R-LOW, SISO-B, 802.11ac80-VHT0, Ch42



BE-R-LOW, SISO-B, 802.11ac160-VHT0, Ch50




BE-R-LOW, SISO-B, 802.11ax20-HE0, Ch36




Date: 7.JAN.2021 16:53:46

BE-R-LOW, SISO-B, 802.11ax40-HE0, Ch38




BE-R-LOW, SISO-B, 802.11ax80-HE0, Ch42




BE-R-LOW, SISO-B, 802.11ax160-HE0, Ch50

## MIMO A




Date: 7 DEC 2010 15:59:33


BE-R-LOW, MIMO-A, 802.11n20-HT8, Ch36



BE-R-LOW, MIMO-A, 802.11n40-HT8, Ch38



BE-R-LOW, MIMO-A, 802.11ac80-VHT0, Ch42




Date: 4 DEC 2010 20:10:28

BE-R-LOW, MIMO-A, 802.11ac160-VHT0, Ch50




Test Report N° 200611-01.TR01




Date: 4 DEC 2020 19:41:10

BE-R-LOW, MIMO-A, 802.11ax20-HE0, Ch36




Date: 4 DEC 2020 19:54:17

BE-R-LOW, MIMO-A, 802.11ax40-HE0, Ch38




BE-R-LOW, MIMO-A, 802.11ax80-HE0, Ch42



Date: 4 DEC 2020 20:05:01


BE-R-LOW, MIMO-A, 802.11ax160-HE0, Ch50

### MIMO B



Date: 14 JAN 2021 18:03:25


BE-R-LOW, MIMO-B, 802.11n20-HT8, Ch36




Date: 7 JAN 2021 18:33:11

BE-R-LOW, MIMO-B, 802.11n40-HT8, Ch38


## Test Report N° 200611-01.TR01



BE-R-LOW, MIMO-B, 802.11ac80-VHT0, Ch42




BE-R-LOW, MIMO-B, 802.11ac160-VHT0, Ch50




Date: 14 JAN 2021 17:43:34


BE-R-LOW, MIMO-B, 802.11ax20-HE0, Ch36



BE-R-LOW, MIMO-B, 802.11ax40-HE0, Ch38




BE-R-LOW, MIMO-B, 802.11ax80-HE0, Ch42




BE-R-LOW, MIMO-B, 802.11ax160-HE0, Ch50

U-NII-2a


SISO A



BE-R-HIGH, SISO-A, 802.11a20-6Mbps, Ch64




BE-R-HIGH, SISO-A, 802.11n20-HT0, Ch64




Date: 4 DEC 2020 18:30:44

BE-R-HIGH, SISO-A, 802.11n40-HT0, Ch62




Date: 4 DEC 2020 17:00:09

BE-R-HIGH, SISO-A, 802.11ac80-VHT0, Ch58




BE-R-HIGH, SISO-A, 802.11ac160-VHT0, Ch50




BE-R-HIGH, SISO-A, 802.11ax20-HE0, Ch64

Test Report N° 200611-01.TR01




Date: 4 DEC 2020 16:49:17

BE-R-HIGH, SISO-A, 802.11ax40-HE0, Ch62




Date: 4 DEC 2020 16:53:39

BE-R-HIGH, SISO-A, 802.11ax80-HE0, Ch58




BE-R-HIGH, SISO-A, 802.11ax160-HE0, Ch50


# SISO B




BE-R-HIGH, SISO-B, 802.11a20-6Mbps, Ch64




BE-R-HIGH, SISO-B, 802.11n20-HT0, Ch64




BE-R-HIGH, SISO-B, 802.11n40-HT0, Ch62




BE-R-HIGH, SISO-B, 802.11ac80-VHT0, Ch58




BE-R-HIGH, SISO-B, 802.11ac160-VHT0, Ch50



BE-R-HIGH, SISO-B, 802.11ax20-HE0, Ch64




BE-R-HIGH, SISO-B, 802.11ax40-HE0, Ch62




BE-R-HIGH, SISO-B, 802.11ax80-HE0, Ch58

Test Report N° 200611-01.TR01




BE-R-HIGH, SISO-B, 802.11ax160-HE0, Ch50

MIMO A




Date: 4 DEC 2010 19:35:42


BE-R-HIGH, MIMO-A, 802.11n20-HT8, Ch64



BE-R-HIGH, MIMO-A, 802.11n40-HT8, Ch62




BE-R-HIGH, MIMO-A, 802.11ac80-VHT0, Ch58




Date: 4 DEC 2010 20:10:40

BE-R-HIGH, MIMO-A, 802.11ac160-VHT0, Ch50







BE-R-HIGH, MIMO-A, 802.11ax20-HE0, Ch64



BE-R-HIGH, MIMO-A, 802.11ax40-HE0, Ch62




BE-R-HIGH, MIMO-A, 802.11ax80-HE0, Ch58




BE-R-HIGH, MIMO-A, 802.11ax160-HE0, Ch50

### MIMO B



BE-R-HIGH, MIMO-B, 802.11n20-HT8, Ch64



BE-R-HIGH, MIMO-B, 802.11n40-HT8, Ch62