

FCC ID: FRWRT-5000P

CT Project: TCB – p12a0008

From: Chris Harvey

Date: 8/21/13

- 1) The Class II Permissive Change cover letter must specify if any hardware changes have been made and how they are implementing the new frequencies/modulations.
[Please refer to updated CIIPC letter.](#)
- 2) The FAA letter lists a single FCC ID number FRWRT-5000P, which is the beginning portion of the 12 FCC ID's in this project, but each also has a '-01' through '-12' at the end. There should be something in this application that links the single FCC ID in the FAA letter to the 12 FCC ID's that actually got approved in December 2012.
[Please refer to "FCC Letter of Attestation_Additional Filings.pdf", & "Letter of Attestation_Configurations_Rev.pdf" for clarification.](#)
- 3) The Description of the EUT's on page 3 of the RF report seems to imply that 11 of the devices are identical and that the only different one is -02, with 2 each. Please update this page to clearly describe the configuration of each model and how they differ from each other.
[Table has been updated to show full configurations of each model. Please refer to updated test report.](#)

[Response by: John Erhard and Jennifer Sanchez](#)

[Submitted by: Jennifer Sanchez](#)

[Date: 8/27/13](#)