

INTERTEK TESTING SERVICES

Report No.: HK10031356-1 Sample No.: 1/1 (Console)

Searching Joystick mode



Date: 8.APR.2010 13:22:10




Date: 8.APR.2010 13:23:33

Code: FCC15C_c / Effective Date: 04 Aug 2009


INTERTEK TESTING SERVICES

Report No.: HK10031356-1 Sample No.: 1/1 (Console)

Searching Joystick mode



Date: 8.APR.2010 13:24:53



Date: 8.APR.2010 13:27:08

Timming Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement

Code: FCC15C_c / Effective Date: 04 Aug 2009