

All the reassurance you need

Tunstall

MODIFICATION LETTER

30th Sep. 2008

TRL Compliance Ltd
Long Green
Forthampton
Gloucester
GL19 4QH
UK

RE: Certification Application
FCC ID: G2X6460411

To Whom It May Concern:

Please be advised that the following information is a list of modifications that will be included in the production process for the above-referenced equipment.

In the US GEM one component is different.

R02 S1160472 RESISTOR 4K7 1% 0W063 0603(LF)

Now we changed it to

R02 S1160103 RESISTOR 10K 1% 0W063 0603(LF)

The above change alters the RF power output of the device to improve battery life, therefore a permissive class II change application is submitted.


Thank you for your attention to this matter.

Yours faithfully

Mike Hodges

R&D director
Tunstall Healthcare (UK) Ltd.

Whitley Lodge, Whitley Bridge
Yorkshire, UK
DN14 0HR
TRI 51F049 iss02B



Tunstall Healthcare (UK) Ltd, Whitley Lodge, Whitley Bridge, Yorkshire DN14 0HR

Telephone: 01977 661234 Fax: 01977 663094

www.tunstallhealth.com