g the Battery

IMPORTANT!

ided 12.8V Lithium Ion battery pack is only PARTIALLY CHARGED prior to shipment and it is recommended the battery be fully charged before first use.



e Charger into a standard indoor electrical outlet. This power unit is intended to be y orientated in a vertical or wall mount position. ne 12.8V rechargeable battery pack securely into the charger (as shown above). Be sure

ws are properly matched. g Status Light will be solid red while battery is charging. When charging is complete,


blink green. will last approximately 10-12 minutes depending on terrain and driving style.


ANT: It is normal for the battery pack to become warm after charging and/or use. Be sure ne battery pack to cool before using or recharging. Recharging a warm battery pack will duce the battery life.

TION PARENTS:

PER USE ons & Care

ery Charger & Battery Pack need to be periodically examined for potential hazards. Any lly hazardous parts need to be repaired or replaced.







OWNER'S MANUA

Please read and understand all precautions prior to us

Thank you for choosing a premium New Bright produ

Trouble Shooting



90% of all difficulties experienced with radio controlled vehicles are due to either weak batteries or batteries that have been installed incorrectly. When batteries become weak, the vehicle may not necessarily stop completely but may exhibit slow response, slow speed or erratic behavior.

Problem - Vehicle does not move or moves slowly.

- Make certain there are fresh alkaline batteries in the transmitter and that they have been installed in the correct position.
- Are the (+) and (-) markings on the alkaline batteries in the same position as the (+) and (-) markings in the Transmitter Battery Compartment?
- Has the Battery Pack been installed in the vehicle?
- Has the rechargeable Battery Pack been fully charged?
- Are the (+) and (-) markings on the Battery Pack in the same position as the (+) and (-) markings in the Battery Compartment?
- Are the metal contact tabs touching, rusty or dirty in the transmitter?
- Make certain that the vehicle ON/OFF switch is in the "ON" position.

Problem - Vehicle moves by itself or exhibits reduced range from the transmitter.

- Make certain there is no outside radio interference in your area. The best way to test this is to take the vehicle as far away from radio towers, electrical lines or tall buildings as possible to ensure no further radio interference will occur.

Cautions

SUPPORT

Do not recharge Battery Pack if it is hot or warm to the touch. Allow Battery Pack to cool before recharging. Recharging a hot or warm Battery Pack will shorten the life of the Pack.

be adjusted. The Steering Trim is located on bottom of chassis between the front wheels.

Do not recharge a Battery Pack if it appears to be damaged or leaking.

Always unplug Charger when not in use.

Always remove Battery Pack from Battery Compartment when not in use.

Do not dispose batteries in fire. Leakage, explosion and personal injury may occur.

Dispose of Rechargeable Battery Pack properly.

Do not attempt to disassemble Battery Pack or Charger.

Do not use Battery Charger for any use other than instructed in this booklet.

Only an adult should charge Batteries.

Do not attempt jumps or tricks with this vehicle.

NOTE: This explanes has been bested and found to comply with the limb for a Class B digital docks, prepared to Part 1,5 of the PCO Pallor. These limbs are designed to provide an appared procedom, pages the manual indeference in a modernal breathers. This explanes of part of the part of the page of the pag

- Recrient or relocate the receiving antenna.

- Increase the separation between the equipment and receiver.

 Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

 Consult the dealer or an experienced radio(TV) technician for help.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

NEW BRIGHT Warranty Information

USA & Canada 30-Day Limited Warranty

New Bright Industries warrants to the original purchaser that this product will be free of defects i materials and workmanship for thirty (30) days from the date of purchase. In the event of such d within the warranty period, New Bright will repair or replace the product at our sole discretion. The warranty does not cover damage resulting from unauthorized modifications, accident, misuse or

Should your item have a defect covered under this warranty, first call the toil free number listed I Most problems can be resolved in this manner. If necessaary, you will be issued a featurn Author number (RA) and instructions on how to obtain a Product Return Form. The Product Return Form. used when returning a product to us (postage pre-paid and insured by the consumer).

When returning a defective product, please package the product, the Product Return Form and the dated sales receipt as proof of purchase. Be sure to mark the RA number on the Product Re-Form. If the product is returned without a dated sales recept, it will be excluded from coverage to warranty. Please allow 4 to 6 weeks for delivery of repaired or replacement vehicles (depending location).

New Bright Industries' liability for defects in materials and workmanship under this warranty shall limited to repair or replacement at our sole discretion. In no event shall we be responsible for inc consequential or contingent damages (except in those states that do not allow this exclusion or

Valid only in the USA & Canada.

Contact New Bright Industries Customer Service Toll Free at: 1-877-NBI-TOYS (1-877-624-8697) Monday through Friday, 8:00 AM to 5:00 PM Eastern Time

U.S. Toy Sales and Marketing Co. Inc. 30260 Oak Creek Drive – 2nd Floor Wixom MI 48393 1-877-624-8697 http://www.newbright.com/

