

**The following changes have been done to the PCB**

**Remove Y4      26.16888MHz**

**Remove C13    27pF**

**Remove C14    27 pF**

**Add Y3            25.6000MHz TCXO**

**Add C13        10nF**

**Add C141       10nF**